Read this before using the Agility Bands

Iron Edge Agility Bands Instructions & Guidelines

Before using Iron Edge Agility Bands

- » Always consult your doctor/physician before commencing any exercise regime. Iron Edge will not be held responsible for any injury or death that occurs while using this product.
- » Check the product for any manufacturing defects prior to use. If defects are evident, do not use the product and contact Iron Edge immediately.
- » Iron Edge recommends seeking assistance from a qualified personal trainer before commencing training.
- » Any resistance band can be dangerous.

Warning: Our Agility Bands are made of latex. It is recommended that people with latex allergies do not expose their skin to Agility Bands.

Product Care:

- » Keep Agility Bands stored in a dry place.
- » Keep Agility Bands out of direct sunlight for prolonged periods. Natural latex is damaged by UV rays.
- » Do not stretch bands beyond one-and-a-half times their original length (i.e. 5 metres total).
- » Avoid looping bands around abrasive surfaces (use a utility strap to tie off safely).
- » Frequently check the condition of your Agility Band. If damage is evident, discontinue use.

Three-month Product Warranty

- » Iron Edge Agility Bands are covered by a three-month warranty for manufacturers' defects and faults.
- » Iron Edge will exchange/replace/refund to the customer's satisfaction all Agility Bands affected by manufacturers defects.
- » This warranty does not include normal wear and tear and aesthetic appearance.
- » This warranty does not include Agility Bands that are subjected to abrasive surfaces, over-stretching or misuse.

Iron Edge No BS Policy.

We take our products and services seriously. It's for this reason we offer a hassle-free No BS policy with all our products. If there's ever an issue with our service or product that is outside of normal wear and tear (see our Terms & Conditions), simply let us know and we'll take care of it with a No BS attitude.

ironedge.com // 1300 85 40 50